Appl. No. 10/616,943 Amdt. dated November 4, 2004 Reply to Office action of August 4, 2004 Page 8

Corrections to the Drawings:

Attached is a correct Fig. 1 adding the label "PRIOR ART" thereto.

Oocket No. 2957-136 Superconducting rotor with cooling system REPLACEMENT SHEET

Fig. 1

PRIOR ART

24

25

28

28

28

28

28

28

29

10


11

10

11

10

Fig. 2



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
COLOR OR BLACK AND WHITE PHOTOGRAPHS
GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
Потить

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.